PRELIMINARY SUMMARY OF MAP ACTIONS

Community: MADISON COUNTY Community No: 180442

To assist your community in maintaining the Flood Insurance Rate Map (FIRM), we have summarized below the previously issued Letter of Map Change (LOMC) actions (i.e., Letters of Map Revision (LOMRs) and Letters of Map Amendment (LOMAs)) that will be affected by the preparation of the enclosed revised FIRM panel(s).

1. LOMCs Incorporated

The modifications effected by the LOMCs listed below have been reflected on the Preliminary copies of the revised FIRM panels. In addition, these LOMCs will remain in effect until the revised FIRM becomes effective.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
			NO CASES RECORDED		

2. LOMCs Not Incorporated

The modifications effected by the LOMCs listed below have not been reflected on the Preliminary copies of the revised FIRM panels because of scale limitations or because the LOMC issued had determined that the lot(s) or structure(s) involved were outside the Special Flood Hazard Area, as shown on the FIRM. These LOMCs will be revalidated free of charge 1 day after the revised FIRM becomes effective through a single revalidation letter that reaffirms the validity of the previous LOMCs.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
LOMA	00-05-0416A	11/12/1999	9312 W 700 SOUTH	1804420007B	18095C0240D
LOMA	00-05-4560A	08/25/2000	W/2, SW/4, SEC 35, 22N, R 6 E; 7862 WEST 1400 NORTH		18095C0087D
LOMA	02-05-1793A		MINI-PLAT NO. 13, LOT 1; 2467 WEST 1300 NORTH	1804420003B	18095C0115D
LOMA	02-05-2305A	05/08/2002	NE CORNER OF SE1/4 NE1/4 OF SECTION 18, T21N, R7E; 11735 NORTH 500 WEST	1804420003B	18095C0095D
LOMA	02-05-2571A		PART OF S28-T21N-R6E; 9745 NORTH STATE ROAD 37	1804420003B	18095C0155D
LOMA	03-05-4408A	07/25/2003	PART OF SEC. 17, T 21 N, R 8 E; 1214 E 1150 N	1804420004B	18095C0120D
LOMA	04-05-0134A	10/29/2003	SECTION 30, T18N, R8E; 8381 SOUTH 75 EAST	1804420008B	18095C0335D
LOMA	04-05-3634A		LOT 39, REPLAT OF LOTS 29-55; 1723 KILLBUCK TRACE	1804420006B	18095C0193D

8/21/2008 Page 1 of 3

PRELIMINARY SUMMARY OF MAP ACTIONS

Community: MADISON COUNTY Community No: 180442

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
LOMA	04-05-A430A	09/15/2004	7996 SOUTH STATE ROAD 109 PORTION OF SECTION 21, T18N, R8E	1804420008B	18095C0335D
LOMA	05-05-1744A	02/25/2005	THE LAKES AT KILLBUCK SUBDIV, SECTION 22, LOT 55 3224 LAKEFRONT LANE	1804420006B	18095C0193D
LOMA	05-05-1816A	03/11/2005	SALYER'S GOLDEN ACRES, TRACT N 148 MCARTHUR COURT	1804420006B	18095C0193D
LOMA	05-05-1219A	03/23/2005	6985 NORTH 750 WEST PORTION OF SECTION 11, T20N, R6E	1804420003B	18095C0155D
LOMA	05-05-5418A	11/22/2005	619 EAST 360 NORTH PORTION OF SECTION 30, T20N, R8E	1804420006B	18095C0195D
LOMA	06-05-C521A	10/12/2006	1966 WEST 950 SOUTH PORTION OF SECTIONS 34 AND 35, T18N, R7E (IN)	1804420008B	18095c0330D
LOMA	07-05-1119A	12/14/2006	FIDDLERS GREEN SIBDIV, SECTION 7, LOT 115 6395 SOUTH CABRIOLET WAY (IN)	1804420008B	18095C0264D
LOMA	07-05-4001A	05/31/2007	PORTION OF SECTION 31, T20N, R8E 2415 ALEXANDRIA PIKE (IN)	1804420006B	18095C0193D
LOMA	07-05-4525A	08/21/2007	A PORTION OF SECTION 28, T21N, R6E 9773 NORTH STATE ROAD 37 (IN)	1804420003B	18095C0155D

3. LOMCs Superseded

The modifications effected by the LOMCs listed below have not been reflected on the Preliminary copies of the revised FIRM panels because they are being superseded by new detailed flood hazard information or the information available was not sufficient to make a determination. The reason each is being superseded is noted below. These LOMCs will no longer be in effect when the revised FIRM becomes effective.

LOMC	Case No.	Date Issued	Project Identifier	Reason Determination Will be Superseded
LOMA	00-05-2224A	04/20/2000	5278 WEST 8TH STREET ROAD	4
LOMA	01-05-1902A	07/11/2001	RIVER EDGE ESTATES, LOT 18; 6615 WEST RYAN RD	4
LOMA	02-05-1754A	04/10/2002	RIVER EDGE ESTATES, LOT 5 AND 6; 6702 WEST RYAN DRIVE	4
LOMA	02-05-3245A	06/19/2002	RIVER EDGE ESTATES REPLAT, LOT 11; 6817 WEST RYAN DRIVE	4
LOMA	03-05-4841A	09/10/2003	PORTION OF SECTION 36, T20N, R6E; 2050 NORTH 700 WEST	4

8/21/2008 Page 2 of 3

PRELIMINARY SUMMARY OF MAP ACTIONS

Community: MADISON COUNTY Community No: 180442

LOMC	Case No.	Date Issued	Project Identifier	Reason Determination Will be Superseded
LOMA	06-05-0219A	12/08/2005	RIVER EDGE ESTATES REPLAT, LOTS 9 & 10 6810 WEST RYAN DRIVE	4
LOMA	06-05-B210A	02/16/2006	1688 NORTH 600 WEST PORTION OF SECTION 6, T19N, R7E (IN)	4
LOMA	07-05-0998A	12/05/2006	RIVER EDGE ESTATES REPLAT, LOT 2 - 6606 WEST RYAN DRIVE (IN)	4
LOMA	07-05-2051A	02/27/2007	RIVER EDGE ESTATES REPLAT SUBDIV, LOT 20 6601 WEST RYAN DRIVE (IN)	4
LOMA	08-05-0746A	12/11/2007	RIVER EDGE ESTATES REPLAT, LOTS 15 & 16 6703 WEST RYAN DRIVE (IN)	4

- 1. Insufficient information available to make a determination.
- 2. Lowest Adjacent Grade and Lowest Finished Floor are below the proposed Base Flood Elevation.
- 3. Lowest Ground Elevation is below the proposed Base Flood Elevation.
- 4. Revised hydrologic and hydraulic analyses.
- 5. Revised topographic information.

4. LOMCs To Be Redetermined

The LOMCs in Category 2 above will be revalidated through a single revalidation letter that reaffirms the validity of the determination in the previously issued LOMC. For LOMCs issued for multiple lots or structures where the determination for one or more of the lots or structures has changed, the LOMC cannot be revalidated through this administrative process. Therefore, we will review the data previously submitted for the LOMC requests listed below and issue a new determination for the affected properties after the effective date of the revised FIRM.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
			NO CASES RECORDED		

8/21/2008 Page 3 of 3